

**महाराष्ट्र शासन**
सार्वजनिक बांधकाम विभाग

**कार्यकारी अभियंता,** यांचे कार्यालय
सार्वजनिक बांधकाम विभाग क्र. १,
रेसिडेन्सी रोड, सदर, नागपूर

दुरध्वनीक्र. ०७१२-२५६५४४९
E-mail ID:- div1nagpur.ee@mahapwd.gov.in

जा.क्र./रे.शा./आरे-१/ /२०२६ ६९६३ दि.३१/०७/२०२६

**प्रति,**

**Bhavan's Bhagwandas Purohit Vidya Mandir**
**Srikrishna Nagar, Khasra No. 51/2, Wathoda,**
**Nagpur-440024**

**विषय :- इमारत सुरक्षीत असल्याचे प्रमाणपत्र देणेबाबत.**

**संदर्भ** :- १. आपले पृ.क्र. ५६२/BBPVM/SHR/KW दिनांक ०६/०६/२०२६.
२. उपविभागीय अभियंता, सार्वजनिक बांधकाम उपविभाग क्र.४, नागपूर यांचा अहवाल पत्र क्र. ८८०/ २०२६ दिनांक ०७/०७/२०२६.

---

संदर्भिय पत्राच्या अनुषंगाने आपल्या **Bhavan's Bhgwandas Vidya Mandir at Sri Krishna Nagar, Khasra No. 51/2, Wathoda Nagpur- 440024** शाळेची इमारत व परिसराची दिनांक २०/०६/२०२६. रोजी उपविभागीय अभियंता, सार्वजनिक बांधकाम उपविभाग क्र. ४, नागपूर यांची मौका पाहणी केलेली आहे. संबंधित संस्थेकडून मूळ प्रस्तावासोबत Fire Safty Certificate तसेच M/s T.P. Mase and Assosiated Chartered Engineers च्या अधिन राहुन इमारत सुरक्षित असल्याचे प्रमाणपत्र सोबत देण्यात येत आहे.

करीता आपल्या माहिती व पुढील कार्यवाहीस्तव सादर.

**सहपत्र** :- प्रमाणपत्र

**(लक्ष्मीकांत राऊळकर)**
**कार्यकारी अभियंता**
**सार्वजनिक बांधकाम विभाग क्र. १,**
**नागपूर**

**प्रतिलिपी** :- उपविभागीय अभियंता, सार्वजनिक बांधकाम उपविभाग क्र.४, नागपूर यांना माहितीस अग्रेषित.

PRINCIPAL
Bhavan's B. P. Vidya Mandir
Srikrishna Nagar, Nagpur-24

Abhutani
Smt. Anju Bhutani
Manager

Drawing Section/DM/2026

**Annexure D**

## BUILDING SAFETY CERTIFICATE

No. 6963 Dated : 31/07/2026

It is Certified that the existing building of **Bhavan's Bhagwandas Purohit Vidya Mandir** at **Srikrishna Nagar, Khasra No. 51/2, Wathoda, Nagpur-440024** is having Block(s)/Floor(s) as per details below :

| Details of Block(s) in school | Block (1) | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|---|---|---|---|---|---|---|
| No. of Floor(s) in the Block | G+4 | - | - | - | - | - |

The building is owned by **Bhavan's Bhagwandas Purohit Vidya Mandir** at **Srikrishna Nagar, Khasra No. 51/2, Wathoda, Nagpur-440024** have compiled with the Building Safety requirements in accordance with National Building code Rule, and verified by the officers concerned of Public Works Division No. 1, Nagpur on **20/06/2026** in the presence of **Shri. Lalit Dinkar Joshi** (Principal, Bhavan's Bhagwandas Purohit Vidya Mandir, Shrikrishna Nagar, Nagpur-440024) and that the building/premises is fit for occupancy for running school with effect from ...../...../**2026** For a period of **1** year in accordance with rule and subject to compliance of the specific conditions as appended.

1. Fire Safety Certificate by NMC, Nagpur. FES/011/CFO Dt. 28/04/2026.
2. Building Photos

Issued on 31/07/2026
at Nagpur by
Strike out whichever is not applicable. In case of block is more than six use seperate sheet for detail.

**(Mukul Deshkar)**
**Sub Divisional Engineer**
**P. W. Sub Division No. 4**
**Nagpur**

**(Laxmikant Raulkar)**
**Executive Engineer**
**Public Works Division No.1**
**Nagpur**

**To,**
**Principal,**
**Bhavan's Bhagwandas Purohit Vidya Mandir,**
**Srikrishna Nagar, Khasra No. 51/2, Wathoda,**
**Nagpur-440024.**

## ENDORSEMENT

The Building Safety Certificate issued by department stand cancelled and annulled due to Earth Quake, Fire or any other Natural Calamities.

**(Mukul Deshkar)**
**Sub Divisional Engineer**
**P. W. Sub Division No. 4**
**Nagpur**

**(Laxmikant Raulkar)**
**Executive Engineer**
**Public Works Division No.1**
**Nagpur**

PRINCIPAL
Bhavan's B. P. Vidya Mandir
Srikrishna Nagar, Nagpur-24

Abhutani